Panasonic


Panasonic Weather Solutions




Panasonic Avionics Corporation











The 2 images show TAMDAR data from flights into/out of BUF +/- ~3h from 10 pm.

The solid triangles indicate icing, and the hollow triangles indicate icing with heaters activated.








The TAMDAR heater <u>remains</u> activated throughout the descent, so the ice accretion rate is > 0.02" / min.

TAMDAR observations around the time of the Colgan crash

Panasonic Aviation Forecasting







Panasonic-AVTECH Wake Vortex Prediction

